



# 6905-5739 Gunmetal Boot Stand - 4 Pair ©2015 Whitmor, Inc.

Полка-держатель для сапог  
стальная. Инструкция по сборке.




**A 1 ea**  
Top wire shelf

Верхняя полка 1 шт.



**B 1 ea**  
Bottom wire shelf

Нижняя полка 1 шт.




**C 1 ea**  
Left side frame

Левая секция  
рамы 1 шт.

**D 1 ea**  
Right side frame

Правая секция  
рамы 1 шт.



**E 1 ea**  
Back frame

Нижняя секция  
рамы 1 шт.



**F 4 ea**  
Hex screw

Винт 4 шт.



**G 1 ea**  
Hex wrench

Ключ 1 шт.

**Assembly  
Time:**  
Less than  
10 minutes.

Изделие  
предназначено для  
хранения сапог.

This product is intended  
for boot storage.

**Tools Needed:** No additional tools required.


Инструмент не требуется.

**STEP 1** Insert left and right side frames (C&D) into ends of back frame (E) until push button snaps into the holes in (E).

Шаг 1. Вставьте правую и левую секции рамы (C и D) в нижнюю секцию (E) до щелчка.

**STEP 2** Position the two wire shelves (A&B) between the left and right side frames (C&D). Align the holes and insert hex screws (F). Tighten with hex wrench (G).

Шаг 2. По очереди прикрутите верхнюю (A) и нижнюю (B) полки к раме винтами (F). Затяните с помощью ключа (G).



Part	Reference
A	F8113
B	F8114
C	F8115
D	F8116
E	F8117
F	F8118
G	F8119

MADE IN CHINA



8680 Swinnea Road • Suite 103 • Southaven, MS • 38671

**NEED HELP?** For help with assembly, or if you are missing a part, please call Whitmor's Customer Service Department, 1-888-944-8667 between 8 a.m. and 4:30 p.m. (Central Standard Time) Monday through Friday. Or email: [help@whitmor.com](mailto:help@whitmor.com). Visit us online at [www.whitmor.com](http://www.whitmor.com)